ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
DASARAHALLI	14	Bagalakunte
Street ID	**Street Name**	**Significant Landmark**
W0811	NA	HAVANOOR LAYOUT
Segment No.	**Total Length (m)**	
14/S-W0811/S012652	195.21	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	195.21	77.503741	13.051556	77.504282	13.053245	W0860	DEAD END

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
IMPROVEMENTS OF DRAIN AT 11TH CROSS OF HAVANOOR LAYOUT	1800000	2013
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Drain Maintenance	
Tender	**Work Details**	**Job No. / Work Code**
Tender		014-13-000010
Work Order No.	**Work Order Date**	**Period of Extention**
EE\DD\WO\106\13-14	12/08/2013	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
		No

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
K.NAGARAJU		1733456.00
Phone No.	**E-Mail ID**	
9448046977		

ಸಹಾಯಕ ಕಾರ್ಯನಿರ್ವಾಹಕ ಅಭಿಯಂತರರು
ದಾಸರಹಳ್ಳಿ ವಲಯ ವಿಭಾಗ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

Field Inspection Details

Number of Trees	Any Other Information	Name
0		Manjunthd -

Date of Inspection	Remarks
07/10/2015	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	SIDDEGOWDRU	07/10/2015	06/11/2015	COMPLETED
EE	MALATHESH D	07/10/2015	06/11/2015	COMPLETED
AEE	RANGASWAMY	07/10/2015	06/11/2015	COMPLETED
AE	MANJUNATH	07/10/2015	06/11/2015	
AE	MANJUNATH	07/10/2015	06/11/2015	COMPLETED

2/14

ಸಹಾಯಕ ಕಾರ್ಯನಿರ್ವಾಹಕ ಅಭಿಯಂತರರು
ದಾಸರಹಳ್ಳಿ ವಲಯ ಬಿಬಿಎಂಪಿ
ಬೈಕಸ್ಟ್ ಸಿಂಗಸಂದ್ರ ಮುಖ್ಯರಸ್ತೆ ಪಾಲಿಕೆ
ಬೆಂಗಳೂರು-560 073.